





Failed Items Details

Report Summary		Vehicle Information		Other Summary	
Report Name	DiagnosticMRI KOEO	VIN	1GCEK19T64E193816	Items Checked	93
Report Number	611	Year	2004	Duration	00:27 (Min:Sec)
Report Time	03/16/2012 3:55 PM	Make	CHEVROLET	Device	EVI-6
Performed By	Erik Horn	Model	SILVERADO 1500	Firmware Version	EVI6_01a
Company ID	55	Engine	5.3 V8 (T)	Script Version	11
		Odometer	96409	Applet Version	1.0.0.15
		Vehicle ID	CALID	Database Version	3/7/2012

CRITICAL ALERTS: NONE

Failed Items Details			
Test	Value	Result	Note
 Battery - FAIL			
Highest Battery Voltage While Testing	12.34 Volts	FAIL	Battery does not appear to be charged properly. Perform appropriate battery load tests to confirm.
Additional Notes			
 Temperatures - FAIL			
ECT to IAT Comparison	19.7 °F	FAIL	Difference between ECT and IAT is too large.
Additional Notes			

VehicleMRI depends on its sources for the accuracy and reliability of this information, therefore, no responsibility is assumed by VehicleMRI or its agents for errors or omissions in this report. VehicleMRI further expressly disclaims all warranties, express or implied, including any implied warranties or merchantability or fitness for a particular purpose. VehicleMRI, CarMRI, AuctionMRI are and their associated logos are Trademarks of VehicleMRI LLC, Copyright 2011-2012, VehicleMRI LLC, All Rights Reserved.

VehicleMRI LLC, Vehicle Research Center Bldg. 2, 187 Commerce Dr, Scott Township, PA 18447
Toll Free : 855-2MRI-NOW (855-267-4669) Phone: 570-241-0769 Fax : 855-221-5620 Support: 570-351-1376
<http://www.vehiclemri.com>